

An error has occurred while processing PictureBox 'pictureUnitLogo1':
Invalid image data.
----- InnerException -----
Parameter is not valid.

BMW IX XDRIVE40 / BMWI-N 4WD

TESTDATO: 11.09.2026

KODE: 2115797

An error has occurred while processing PictureBox 'pictureBoxRegNumberSw':
Invalid image data.
----- InnerException -----
Parameter is not valid.



22 546 KM

CHASSISNR: WBY11CF04RCP06621

BRUKTIMPORT: Nei

KJØRETØY: Personbil

FRIST FOR PKK: 23.08.2027

NBF Tilstandsrapport er utarbeidet av Norges Bilbransjeforbund og Forbrukerrådet.

NBF Tilstandsrapport gir en detaljert beskrivelse av bilens tilstand, og gir den som kjøper bilen økt trygghet ved kjøpet. Rapporten utarbeides av teknisk kyndig personell, som gjør en grundig kontroll og inspeksjon.

Tilstandsrapporten beskriver bilens tilstand på testtidspunktet hensyntatt bilens alder og kilometerstand, med det utstyret som er i og på bilen.

Se mer om forutsetningene for vurderingen og andre vilkår på siste side.



Med-deg-hele-veien

OPPSUMMERT STATUS PÅ KJØRETØY

Ingen anmerkning

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



IDENTITET

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



EKSTERIØR

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



MOTOR

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



BREMSER

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



INTERIØR

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'picturePartnerLogo1':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox3':
Invalid image data.
----- InnerException -----
Parameter is not valid.

23.08.2023
Førstegang registrert



An error has occurred while processing PictureBox 'pictureBox16':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



ASSISTENTSYSTEMER OG DIAGNOSE

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



LYS

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



HJULOPPHENG/STYRING

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



GIR OG DRIVLINJE

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.

An error has occurred while processing PictureBox 'pictureBox12':
Invalid image data.
----- InnerException -----
Parameter is not valid.



OPPLEYSNINGER/KLARGJØRING

An error has occurred while processing PictureBox 'pictureBox15':
Invalid image data.
----- InnerException -----
Parameter is not valid.






TILSTANDSRAPPORT

Elektr.

An error has occurred while processing PictureBox 'pictureBox4':
Invalid image data.
----- InnerException -----
Parameter is not valid.





Anmerkning(er)




An error has occurred while processing PictureBox 'pictureUnitLogo4':
Invalid image data.
----- InnerException -----
Parameter is not valid.






An error has occurred while processing PictureBox 'picturePartnerLogo4':
Invalid image data.
----- InnerException -----
Parameter is not valid.

INFORMASJONSBLIDER









BMW i

BATTERY HEALTH QUICK REPORT.

This quick evaluation is based on algorithms of the high-voltage battery software in the vehicle and does not represent a binding result, but merely an indication of the current remaining capacity of the high-voltage battery. In particular, the report does not replace the detailed measurement as part of a "Battery Health Certificate".

Vehicle identification number:	WBY11CF04RCP06621
Date:	28/08/2020 10:37
Housing no. high-voltage battery:	
Retailer number / diagnosis tester:	30702 / SPIISCBTH18
Vehicle mileage:	22946.0 km
Battery capacity:	Stamp, signature:
100%	

The specified capacity indicates the battery capacity available in the vehicle compared to its new condition and represents only the value at the time of diagnosis. This value is determined by the battery management system. The specification does not allow any predictions to be made about the further development of the battery capacity, which is largely determined by individual driving behavior and external influences. The capacity determination in the vehicle is subject to a certain degree of variation due to the nature of the system, which varies depending on the battery generation. This vehicle is equipped with a high-voltage battery generation that has a maximum variation of 2% in at least 95% of reference measurements. The value determined does not justify any warranty or guarantee claims.

An error has occurred while processing PictureBox 'pictureUnitLogo5':
Invalid image data.
----- InnerException -----
Parameter is not valid.

KJØRETØYDATA

ANTALL NØKLER	2	ANTALL LADEKABLER	2
TIDLIGERE STØRRE SKADE	Nei	TIDLIGERE BRUK	Normal bruk

PRØVEKJØRING

PRØVEKJØRT	HASTIGHET	TESTFORHOLD
Ja	80	Tørt

DEKK OG BREMSER

PRODUKSJONSDATO SOMMERDEKK	Uke 23, 2023	PRODUKSJONSDATO VINTERDEKK	Uke 49, 2021
----------------------------	--------------	----------------------------	--------------

	VENSTRE FORAN	HØYRE FORAN	VENSTRE BAK	HØYRE BAK
MØNSTERDYBDE SOMMERDEKK (MM)	6	6	5,8	5,9
MØNSTERDYBDE VINTERDEKK (MM)	8,4	8	7,8	8,4
BREMSESKIVER (MM)	35,2	35,2	23,1	23,1
BREMSEKLOSSER (MM)	15	15	10	10

SERVICEINFORMASJON

KOMPLETT HISTORIKK	ELEKTRONISK SERVICEHEFTE
Ja	Ja
SISTE SERVICEDATO	KILOMETERSTAND
22.08.2025	14797
SERVICER UTFØRT	KILOMETERSTAND
17.08.2023	9

An error has occurred while processing PictureBox 'picturePartnerLogo5':
Invalid image data.
----- InnerException -----
Parameter is not valid.

TESTFORHOLD/DATA

An error has occurred while processing PictureBox 'pictureUnitLogo6':
Invalid image data.
----- InnerException -----
Parameter is not valid.

IDENTITET

- ✓ Kjennermerke
- ✓ Understellsnummer
- ✓ Dokumentasjon utstyr/godkjenning
- ✓ Nøkler

ASSISTENTSYSTEMER OG DIAGNOSE

- ✓ Kamera
- ✓ Sensor
- ✓ Systemfunksjoner
- ✓ Diagnose
- ✓ Prøvekjøring

EKSTERIØR

- ✓ Lakk
- ✓ Antirustbehandling
- ✓ Under bil
- ✓ Panser
- ✓ Dører
- ✓ Bakluke
- ✓ Låser/tyverisikring
- ✓ Skjermer
- ✓ Speil
- ✓ Korrosjon
- ✓ Vinduspussere/-spyler
- ✓ Verktøy/nødutstyr
- ✓ Dekk/Felger
- ✓ Hjulmuttere/-bolter
- ✓ Døråpning
- ✓ Terskler/innlastningssone
- ✓ Støtfanger
- ✓ Grill
- ✓ Tak
- ✓ Frontvindu
- ✓ Vinduer
- ✓ Kanal
- ✓ Stolpe
- ✓ Alle flater
- ✓ Ladeluke/tanklokk

LYS

- ✓ Lys foran
- ✓ Lys bak
- ✓ Markeringslys
- ✓ Retningslys
- ✓ Nødsignallys
- ✓ Parkeringslys
- ✓ Refleks
- ✓ Andre lys

MOTOR

- ✓ Batteri(er)
- ✓ El/hybrid batteripakke
- ✓ Elektroniske styresystemer
- ✓ Lekkasjer
- ✓ Motorfester/-demper
- ✓ Service
- ✓ Startmotor
- ✓ Trekkraft

HJULOPPHENG/STYRING

- ✓ Retningsstabilitet/selvoppretting
- ✓ Ratt/styringsmekanisme
- ✓ Hjullager
- ✓ Fjærer/støtdemper
- ✓ Ledd
- ✓ Stabilisatorer/stag
- ✓ Forstilling
- ✓ Bakstilling

BREMSER

- ✓ Bremsfunksjon
- ✓ Parkeringsbrems
- ✓ Bremskraftforsterker
- ✓ Bremsvæske
- ✓ Lekkasjer
- ✓ Rør/slanger
- ✓ Skiver
- ✓ Bremseskjold

GIR OG DRIVLINJE

- ✓ Girkasse
- ✓ Differensial
- ✓ Aksler
- ✓ Fordelingskasse

INTERIØR

- ✓ Dashbord
- ✓ Instrumenter og brytere
- ✓ Midtkonsoll/midtarmlene
- ✓ Dørtrekk
- ✓ Seter
- ✓ Taktrekk
- ✓ Teppet/bekledning
- ✓ Vindusheiser
- ✓ Bilbelte
- ✓ Varme/AC/Klima
- ✓ Signalhorn/Lydsignal
- ✓ Multimedia
- ✓ Multifunksjonsratt
- ✓ Ratt
- ✓ Deksel

OPPLYSNINGER/KLARGJØRING

- ✓ Opplysninger
- ✓ Interiør
- ✓ Øvrig utstyr/klargjøring
- ✓ Annet

An error has occurred while processing PictureBox 'picturePartnerLogo6':
Invalid image data.
----- InnerException -----
Parameter is not valid.

☐ Ikke kontrollert ☒ Kontrollert ☐ Kontrollert, anmerkning

PUNKTER KONTROLLERT

Det tas forbehold om mulige avvik i kontrollpunktene avhengig av biltype og modellvariant

Vilkår, tilstandsrapport

Hva som er vurdert, forutsetninger for vurderingen

Tilstandsrapporten beskriver bilens tilstand på testtidspunktet med det utstyret som var i og på bilen.

Den tekniske vurderingen av bilen er gjort med utgangspunkt i bilens alder og kjørelengde. Rapporten beskriver om bilens tilstand vurderes som normal ut fra bilens alder og kjørelengde og/eller om det er anmerkninger eller øvrige kommentarer. Kontrollpunktene som er vurdert er listet opp i rapporten.

Bilen er ikke demontert ved vurderingen, og tilstandsrapporten påpeker dermed ikke eventuelle feil som kun kan avdekkes ved demontering eller ved lengre tids bruk ut over ordinær prøvekjøring.

Kapasiteten på driftsbatteriet på el- og hybridbiler er ikke målt, og er derfor ikke en del av tilstandsrapport

Feilmeldinger som bilens produsent har gitt tilgang til og som er tilgjengelige på vurderingstidspunktet/testtidspunktet er avlest. Avlesing av feilmeldinger skjer med tilgjengelig diagnoseutstyr. Ved usikkerhet omkring feilkodene anbefales videre undersøkelser.

Bilen er prøvekjørt, men kun ved en kortere tur. Tekniske egenskaper ved bilen som forutsetter spesielle kjøreforhold er kun vurdert om kjøreforholdene på vurderingstidspunktet gjorde dette mulig.

Periodiske feil og avvik for eksempel ved oljeforbruket på fossile biler kan forekomme uten at dette kan avdekkes, ettersom vurderingen kun gir et øyeblikksbilde av bilens tilstand.

Ansvar for utsteder av tilstandsrapporten

Tilstandsrapporten er utarbeidet etter oppdrag fra Oppdragsgiveren. Den konkrete tilstandsrapporten tilhører Oppdragsgiveren og vil ikke bli utlevert til tredjemenn uten samtykke fra Oppdragsgiveren

Utsteder av tilstandsrapporten har ikke ansvar for feil gjort ved alminnelig uaktsomhet. For feil gjort ved grov uaktsomhet eller forsett har utsteder av tilstandsrapporten ansvar for dokumentert direkte, påregnelig økonomisk tap forårsaket av feilen.

Sted og Dato

Sted og Dato

Signatur selger

Signatur kjøper

Selger og kjøper bekrefter med sine underskrifter at ved inngåelsen av kjøpsavtalen ble tilstandsrapporten gjennomgått med kjøper, og at det spesielt ble informert om avvik fra kravene i forbrukerkjøpslovens § 15 i de tilfeller slike fremkommer i rapporten, og at kjøper aksepterer disse avvikene.

