

Erikstadveien 75
8206 FAUSKETlf.: 918 20 840
Fax:Foretaksregisteret
OrgNr: NO 927 904 284 MVA web:

Epost: post@saltenauto.no

KONTANTFAKTURA

Anne Mathilde Wassmo Dobakk
Lyngveien 17
8209 FauskeNUMMER....: 9208
DATO.....: 05.08.25 15:54
SIDE.....: 1
KUNDENR...: 12176
ORDREN...: 9241

MERKE:	MODELL:	REG.NR.	KM	CHASSISNR:	REKV.NR:	VÅR REF.:
MERCEDES-B	GLA 220 CDI 4MATIC	CF75584	159743	WDC1569051J003423		

Varenummer	Tekst	Antall	Stykkpris	I Alt Eks.Mva
Skiftet bremseskiver og klosser foran				
HP T2149	Bremseklosser	1,00	1 074,00	1 074,00
OJD-WS 0162 A	Slitasjevarsel	1,00	206,00	206,00
09.B436.41	Bremsekive	2,00	1 250,00	2 500,00
AT	Arbeid	1,40	1 352,00	1 892,80
VM	Verkstedsmateriell	1,40	48,00	67,20

AutoMester

I ALT
5 740,00NETTO
5 740,00

GRUNNLAG

MVA-FR.	MVA-PL.	25% MVA
5 740,00	1 435,00	

Å BETALE
7 175,00

Erikstadveien 75
8206 FAUSKETlf.: 918 20 840
Fax:Foretaksregisteret
OrgNr: NO 927 904 284 MVA web:

Epost: post@saltenauto.no

KONTANTFAKTURA

Anne Mathilde Wassmo Dobakk
Lyngveien 17
8209 FauskeNUMMER....: 7762
DATO.....: 27.11.24 15:57
SIDE.....: 1
KUNDENR...: 12176
ORDREN...: 7758

MERKE:	MODELL:	REG.NR.	KM	CHASSISNR:	REKV.NR:	VÅR REF.:
MERCEDES-B	GLA 220 CDI 4MATIC	CF75584	152197	WDC1569051J003423		

Varenummer	Tekst	Antall	Stykkpris	I Alt Eks. Mva
	Diagnose			
	- Oppkobling av computer			
	- Utlesning av feilkoder etc.			
	- Sletting av koder			

	Kontroller batteri			

	Funnet defekt batteri			

	Skiftet batteri			
BAT SK820	Sønnak agm batteri 82ah	1,00	3 200,00	3 200,00
AT	Arbeid	0,80	1 232,00	985,60
VM	Verkstedsmaterie11	0,80	48,00	38,40

AutoMester

I ALT	NETTO	GRUNNLAG	MVA-FR.	MVA-PL.	25% MVA	Å BETALE
4 224,00	4 224,00		4 224,00	1 056,00		5 280,00

Erikstadveien 75
8206 FAUSKETlf.: 918 20 840
Fax:Foretaksregisteret
OrgNr: NO 927 904 284 MVAEpost: post@saltenauto.no
web:

KONTANTFAKTURA

Anne Mathilde Wassmo Dobakk
Lyngveien 17
8209 FauskeNUMMER....: 7671
DATO.....: 13.11.24 15:48
SIDE.....: 1
KUNDENR...: 12176
ORDREN...: 7654

MERKE:	MODELL:	REG.NR.	KM	CHASSISNR:	REKV.NR:	VÅR REF.:
MERCEDES-B	GLA 220 CDI 4MATIC	CF75584	151968	WDC1569051J003423		

Varenummer	Tekst	Antall	Stykkpris	I Alt Eks.Mva
Service 150 000km				

	Skiftet motorolje m/filter			
	Skiftet luftfilter			
	Skiftet dieselfilter			
	Skiftet kupefilter			
	Skiftet batteri nøkkel			

	Funnet defekt støvmansjett på støtdemper høyre foran			
FIL 0X1537D2	Knecht oljefilter innsats	1,00	330,00	330,00
FIL LX3471	Knecht luft filter	1,00	830,00	830,00
FIL LAK879	Knecht kupe filter comfort	1,00	807,00	807,00
FIL KL911	Knecht drivstoff filter	1,00	1 765,00	1 765,00
SV	Spylevæske	3,00	24,00	72,00
TOT 213818	QUARTZ INEO L LIFE 5W30 1L	6,50	280,00	1 820,00
FR	Frakt	1,00	180,00	180,00
DR	Common Rail Diesel Syst Clean&	1,00	280,00	280,00
BATN	Batteri nøkkel	1,00	80,00	80,00
AT	Arbeid	3,00	1 232,00	3 696,00
VM	Verkstedsmateriell	3,00	48,00	144,00

GRUNNLAG

I ALT	NETTO	MVA-FR.	MVA-PL.	25% MVA	Å BETALE
10 004,00	10 004,00	10 004,00	2 501,00		12 505,00

DOBAKK, ANNE MATHILDE
LYNGVEIEN 17

8209 - FAUSKE

M Nordvik AS, avd Bodø Stormyra

M Nordvik AS

Stormyrveien 23, , 8000 Bodø

Telefon: 75514000

Foretaksnr: NO 960 852 338 MVA

Kontantfaktura

Side 1 (1)

Merke	MER/MERGLA	Rep.dato	09.11.2023	Fakturanr.	CD26500078533
Regnr.	CF75584	Kilometerstand	140989	Fakturadato	10.11.2023
Chassisnr.	WDC1569051J003423	Reg.dato	27.10.2014	Kundenr.	2156268
Eier	Dobakk, Anne Mathilde	Vår ref.	Tore Kvalnes	Arbeidsordre	9130340
Bruker		Deres ref.		Serie nr.	201330315

Art nr	Beskrivelse	Ant.	Stk.Pris eks.mva	Andel%	Rab%	Beløp inkl. mva.
--------	-------------	------	---------------------	--------	------	------------------

Periodisk Kjøretøykontroll

Arbeid

PKK

Sum

Fastpris

1

990,00

Service

SERVICE A - PLUS PAKKE

Arbeid	001157	Utført Service A med Plusspakke			15	1 861,81
Arbeid	001207	Tilleggsarbeid ved service: Smurt, rengjort panoramasoltakmekanikk			15	413,74
Materiell	A002986147109	SPYLEVÆSKE KONSENTRAT, 1 L VINTER	1	133,01	15	141,33
Materiell	A6511800109	OLJEFILTERINNSATS	1	449,31	15	477,39
Materiell	436-VA2008002	synpower 5w30 229,51	6.5	175,00	15	1 208,59
Sum						4 102,86

funnet på service

det er ca 5mm klosser forran

Påslagspris

Verkstedmateriell	133,87
Kildesortering	43,01
Miljøgebyr	43,01
Myntavrunding	0,25

Deres oppdrag ble ivaretatt av Tore Kvalnes

Arbeid	Deler	Pliktig	Fritt (*)	Sum eks.mva	Mva	Sum inkl.mva
3 265,55	1 827,31	4 250,17	0,00	4 250,17	1 062,58	5 313,00
Bankkonto	Kidnummer	SWIFT/BIC	IBAN	Betalingsfrist		
1503.39.11499	6768265000785335	DNBANOKKXXX	NO92 1503 3911 499			



DOBAKK, ANNE MATHILDE
LYNGVEIEN 17

8209 - FAUSKE

M Nordvik AS, avd Bodø Stormyra
M Nordvik AS

Stormyrveien 23, , 8000 Bodø

Telefon: 75514000

Foretaksnr: NO 960 852 338 MVA


Kontantfaktura Side 1 (1)

Merke	MER/MERGLA	Rep.dato	07.11.2023	Fakturanr.	CD26500078534
Regnr.	CF75584	Kilometerstand	140989	Fakturadato	10.11.2023
Chassisnr.	WDC1569051J003423	Reg.dato	27.10.2014	Kundenr.	2156268
Eier	Dobakk, Anne Mathilde	Vår ref.	Bjørn Helge Karstensen	Arbeidsordre	9020137
Bruker		Deres ref.		Serie nr.	201330315

Art nr	Beskrivelse	Ant.	Stk.Pris eks.mva	Andel%	Rab%	Beløp inkl. mva.
Lekker mye olje.(Kommer på berger)						
Arbeid	Kontrollert og funnet stor oljelekkasje fra orådet rundt turbo. må demonteres mye for videre kontroll da det ikke går å komme til. 11.10.23				15	413,74
Arbeid	SK, ser ut til at det lekker fra registerstrammer. Kjedestrammer, ut, inn, skifteved behov				15	4 551,11
Sum						4 964,85
						Påslagspris
Verkstedmateriell						292,05
Myntavrunding						0,10

Deres oppdrag ble ivaretatt av Bjørn Helge Karstensen

Arbeid	Deler	Pliktig	Fritt (*)	Sum eks.mva	Mva	Sum inkl.mva
4 964,85	0,00	4 205,52	0,00	4 205,52	1 051,38	5 257,00
Bankkonto	Kidnummer	SWIFT/BIC	IBAN	Betalingsfrist		
1503.39.11499	6768265000785343	DNBANOKKXXX	NO92 1503 3911 499			



Anne Mathilde Wassmo Dobakk
Lyngveien 17
8209 Fauske

Fakturanr.: **86078841** Fakturadato: **26.05.2023**
Ordrenr.: **13796676** Forfallsdato: **26.05.2023**
Km.stand: **137482** Kundenr.:
Reg.nr./ Chassisnr.: **CF75584/ WDC1569051J003423**

Opr./ Delenr.	Beskrivelse	Stk.pris (ekskl.mva.)	Ant.	Rab.	Mva.	Sum (inkl. mva.)
Z1199	Utført. Kontr. alle hjulbolter og alle nav. kunde mener der er flere om er defekte. (I alle fall høyre foran)					
Z1199	Kontr. alle hjulbolter og alle nav. kunde mener der er flere om er defekte. (I alle fall høyre foran)		Arbeid		25 %	1 666,25
		Sum ekskl. mva.: 1 333,00	Mva.: 333,25	Sum inkl. mva.:		1 666,25

Notat til Utført. Kontr. alle hjulbolter og alle nav. kunde mener der er flere om er defekte. (I alle fall høyre foran)

Lag deleliste over hva vi må ha nytt.

-Må ha nye nav begge sider foran og nye hjulbolter. Anbefaler å skifte ut alle hjulbolter da mange er strukket og har dårlige gjenger.

Z1199	Utført Kontroll av bremses foran og bak. Kunde har fått tilbakemelding fra service (annet verksted) at disse er mye slitt.					
Z1199	Kontroll av bremses foran og bak. Kunde har fått tilbakemelding fra service (annet verksted) at disse er mye slitt.		Arbeid		25 %	499,88
		Sum ekskl. mva.: 399,90	Mva.: 99,97	Sum inkl. mva.:		499,88

Notat til Utført Kontroll av bremses foran og bak. Kunde har fått tilbakemelding fra service (annet verksted) at disse er mye slitt.

Finer at bremseskiver foran er mye slitt og bør byttes ved neste skifte av bremseklosser.

Z1199	Forsøke å demontere/bore ut hjulbolter venstre side foran, disse går bare rundt.. Skift forhjulsnav og hjullager begge sider foran samt nye hjulbolter til alle hjul.					
Z1199	Skift forhjulsnav og hjullager begge sider foran samt nye hjulbolter (alle)		Arbeid		25 %	7 281,51
D1	FEB 18913 Forsenket hjulbolt	54,00	20,00 stk		25 %	1 350,00
D1	LAG VKBA 6785 hjullager	1 150,00	2,00 stk		25 %	2 875,00
D1	1202-45000 Hjulnav, Hjulnav foran	1 168,00	2,00 stk		25 %	2 920,00
		Sum ekskl. mva.: 11 541,21	Mva.: 2 885,30	Sum inkl. mva.:		14 426,51

42099-120950	Utført * Hjulstillingskontroll med justering av spissing					
42099-120950	* Hjulstillingskontroll med justering av spissing		Arbeid	10 %	25 %	1 800,00
		Sum ekskl. mva.: 1 440,00	Mva.: 360,00	Sum inkl. mva.:		1 800,00

Notat til Utført * Hjulstillingskontroll med justering av spissing

Dekk venstre side foran er utslitt. Helt inn til cord.

Din kontaktperson: **Tor Kenneth Jordbro** Direkte telefon: E-post: **tor.jordbro@nordvik.no**

Dersom ikke annet er oppgitt er det benyttet originale Toyota deler.



Mercedes-Benz

DOBAKK, ANNE MATHILDE
LYNGVEIEN 17

8209 - FAUSKE

M Nordvik AS, avd Bodø Stormyra
M Nordvik AS

Stormyrveien 23, , 8000 Bodø

Telefon: 75514000

Foretaksnr: NO 960 852 338 MVA

Kontantfaktura

Side 1 (1)

Merke	MER/MERGLA	Rep.dato	06.12.2022	Fakturanr.	CD26500056677
Regnr.	CF75584	Kilometerstand	129873	Fakturadato	06.12.2022
Chassisnr.	WDC1569051J003423	Reg.dato	27.10.2014	Kundenr.	2156268
Eier	Dobakk, Anne Mathilde	Vår ref.	Anniken Sæthre	Arbeldsordre	8022081
Bruker		Deres ref.		Serie nr.	201330315

Art nr	Beskrivelse	Ant.	Stk.Pris eks.mva	Andel%	Rab%	Beløp inkl. mva.
Service B5						
Arbeid	001201	Tillegg ved service: Kontrollert tilhengerfeste				218,63
Arbeid	001158	Utført Service B med Plusspakke				3 279,38
Arbeid	001168	Tillegg ifm service; luftfilterbytte, utført				655,88
Arbeid	001196	Tillegg ved service B: Skiftetbremsevæske				1 093,13
Arbeid	001171	Tillegg ved service: Skiftet drivstoffilter				655,88
Materiell	A651180010990	OLJEFILTERINNSATS	1	282,02		352,53
Materiell	436-VA2008002	synpower 5w30 229,51	6.5	169,00		1 373,13
Materiell	A6510940204	LUFTFILTERINNSATS	1	874,75		1 093,44
Materiell	A642090605290	DRIVSTOFFILTER	1	1 933,52		2 416,90
Materiell	A000989560511	BREMSEVÆSKE, 1 LITER	1	334,55		418,19
Materiell	436-A0029861471	Spylervæske	1.7	61,00		129,63
Sum						11 686,72

Funnet på service

1. Lite klosser foran det er også stor slitekant på skivene. Skiver og klosser foran må skiftes når varsel på bremsebelegg dukker opp.

2. Førstehjelpsskrin er utgått på dato: 19.01.2019

3. Dekkskum er gått ut på dato: 12.2017

	Påslagspris
Kildesortering	115,68
Verkstedmateriell	295,18
Miljøgebyr	115,68
Myntavrunding	-0,26

Deres oppdrag ble ivaretatt av Anniken Sæthre

Arbeid	Deler	Pliktig	Fritt (*)	Sum eks.mva	Mva	Sum inkl.mva
5 902,90	5 783,82	9 770,56	0,00	9 770,56	2 442,70	12 213,00
Bankkonto	Kidnummer	SWIFT/BIC	IBAN	Betalingsfrist		
1503.39.11499	6768265000566776	DNBANOKKXXX	NO92 1503 3911 499			



Mercedes-Benz

Digital Service Report

Note: Please treat this document confidentially!

Vehicle info

Vehicle GLA 220 CDI 4MATI
First reg. date 27.10.2014
FIN WDC 156905 1J 003423

Next 12.2023
Service 154873 km

(Please note the additional information in your vehicle (owner's manual, service booklet and service interval indicator) on the performance of the next service)

Last Servicereport

Mercedes-Benz M Nordvik AS, avd. Bodø Stormyra Date 06.12.2022
Stormyrveien 23 Rep.-order-no. 8022081
Bodø Mileage 129873 km

Performed services

Service Service B
Workshop code 5W031
Remaining time -4 Days
Remaining distance 3890 km

Oil quality/viscosity

Description Engine oil
Viscosity 5W-40
Oil quality 229.5

Replaced / renewed

Air filter element replaced ☒
Fuel filter replaced ☒
Engine: oil and filter change ☒
Brake fluid replaced ☒

Until next service

Mercedes-Benz Mobilo ☒
Warr. against rusting through ☒

Service-intervals in accordance with Mercedes-Benz AG specification

Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification

Accomplished ☒

M Nordvik AS
Stormyrveien 21, 8008 Bodø

Org.nr. 960 852 333

22.12.2022 14:00

Signature / stamp of the workshop



Mercedes-Benz

Service history

Mercedes-Benz	M Nordvik AS, avd. Bodø Stormyra Stormyrveien 23 Bodø	Date	02.12.2021
		Mileage	108763 km
		Service	Service A
Mercedes-Benz	Star Autoco Bodø AS Gamle Riksvei 19/21 BODØ	Date	25.11.2020
		Mileage	89006 km
		Service	Service B
Mercedes-Benz	Star Autoco Bodø AS Gamle Riksvei 19/21 BODØ	Date	06.12.2019
		Mileage	72386 km
		Service	Service A
Mercedes-Benz	Nordic Bil AS Gamle Riksvei 19/21 BODØ	Date	23.10.2018
		Mileage	55742 km
		Service	Service B
Mercedes-Benz	Nordic Bil AS Gamle Riksvei 19/21 BODØ	Date	18.10.2017
		Mileage	39253 km
		Service	Service A
Mercedes-Benz	Star Autoco AS Solheimveien 62 Lørenskog	Date	18.10.2016
		Mileage	28615 km
		Service	Service B
Mercedes-Benz	Star Autoco AS Solheimveien 62 Lørenskog	Date	21.10.2015
		Mileage	12341 km
		Service	Service A

Model 156

Service B with Plus package



P00.20-2756-11

Customer: -

Order number: -

VIN/license plate number: WDC1569051J003423

Kilometers: 129873

Service code: -

Workshop code: 5W031

Remaining distance: -

Remaining time: -

Oil type/viscosity: -

Completion time/date: 06.12.2022

*Recommend Mercedes-Benz oil

Service consultation performed at vehicle

Yes: -

No: X

Notes/explanations: -

Engine oil fill capacity: 6,5 l Without code U43 | 6,1 l With code U43

The following activities are hereby confirmed:

- Completion of relevant service operations

Signature

B	Input condition not OK:	⊗
Completed		
☒		
↓		
☒	Service reception The reception report for service on the vehicle is available in completely edited form	○
	i To be performed by the Service Advisor (where market-specific conditions require). Fully process all acceptance items and the maintenance items listed in the service sheet, only then is the service scope completely performed.	AP00.20-P-0009Z
General		

☒	Methods for conducting all subsequent service items known	Methods not known ↓ See document references to each of the methods in Overview of service overviews	AP00.20-P-1600UGM
☒	Brake system Perform brake test and enter the result in the table		☐
☒	Vehicle exterior Check exterior lights for proper operation		☐
☒	Check operation of headlamp range adjustment	Vehicles with xenon or dynamic LED headlamps or headlamp range controller on the exterior lights switch	☐
☒	Check/correct headlamp adjustment	The adjustment of headlamps on vehicles with XENON or dynamic LED headlamps is to be invoiced as an additional operation.	☐
☒	Vehicle interior Check windshield wipers, windshield washer system and headlamp cleaning system for proper operation		☐
☒	Replace activated charcoal particle filter		
☒	Engine compartment Brake system: Check fluid level		☐
☒	Check low-temperature circuit coolant level	Engines with separate coolant expansion reservoir for low-temperature circuit	☐
☒	Check all visible parts in engine compartment for damage and leaks		☐
☒	Check poly-V-belt in visible area for signs of wear		☐
☒	Underside of vehicle Check all visible parts of vehicle underside for damage and leaks	The country-specific regulations for mobility and body shell complaints apply.	☐
☒	Check condition of steering and tie rods		☐
☒	Check condition of front axle and front axle ball joints		☐
☒	Check condition of propeller shaft and flex disks	With code M005 (4MATIC)	☐
☒	Check condition of rear axle and rear axle ball joints		☐
☒	Check condition of suspension struts or shock absorbers and springs		☐
☒	Check tires for damage and crack formation and enter result in table		☐
☒	Plus package: Tires Correct tire pressure and enter set tire pressure in table		☐
☒	Plus package: Trunk Check/correct spare wheel tire pressure and enter set tire pressure in table	Vehicles with spare tire	☐
☒	Check TIREFIT tire sealant	UTGAT Vehicles fitted with TIREFIT Enter TIREFIT expiration date here: 12.2017	☒
☒	Check first aid bag	UTGAT	☒

i Enter first aid bag expiration date here: 19.06.2019

i Replace first aid bag, invoice as an additional operation.

☒	Check trunk illumination for proper operation	 ○
☒	Plus package: Engine compartment Windshield washer system: Check/correct fluid level	i When using cleaning compounds for summer/winter, and depending on the ambient temperature, observe the mixing ratio.
☒	Plus package: Vehicle interior Check lamps in the instrument cluster and interior illumination for proper operation	 ○
Additional operations		
Service 3		
☒	Engine compartment Engine: Change oil and filter	
Service 4		
☒	Engine compartment Replace brake fluid	
Service 8		
☒	Engine compartment Replace air filter element	
Service 11		
☒	Engine compartment Replace fuel filter	
Service 15		
☒	Vehicle front end, vehicle rear end Trailer hitch: check condition and function	 ○

Brake values

	Left	Right
Front	OK	OK
Rear		
Parking brake		

Tire condition

	Right front	Left front	Right rear	Left rear
Condition OK.	✓	✓	✓	✓
Condition not OK.				

Set tire pressure in bar or psi

	Front axle	Rear axle	Spare wheel
bar/psi	2.5	2.5	