BMW

BATTERY HEALTH QUICK REPORT.

This quick evaluation is based on algorithms of the high- voltage battery software in the vehicle and does not represent a binding result, but merely an indication of the current remaining capacity of the high- voltage battery. In particular, the report does not replace the detailed measurement as part of a "Battery Health Certificate".

Vehicle identification number:	WBY31AW07NFL95417
Date:	13/05/2026 19:54
Housing no. high- voltage battery:	
Retailer number / diagnosis tester:	46430 / ISPIBMOB02
Vehicle mileage:	94249 km

Battery capacity:	Stamp, signature:
96%	

The specified capacity indicates the battery capacity available in the vehicle compared to its new condition and represents only the value at the time of diagnosis. The value is determined by the battery management system. The specification does not allow any predictions to be made about the further development of the battery capacity, which is largely determined by individual driving behavior and external influences. The capacity determination in the vehicle is subject to a certain degree of variation due to the nature of the system, which varies depending on the battery generation. This vehicle is equipped with a high- voltage battery generation that has a maximum variation of 5% in at least 95% of reference measurements. The value determined does not justify any warranty or guarantee claims.